

Rock wall face as viewed from the clearing below. This view is from the area that is most likely available for development of amenities such as restrooms, parking, etc.



The top of the wall provides views of Clackamas River and beyond. This area is only accessible by an experienced climber or hiker, or by a road that is currently only available for timber use.

Wetlands border the western property line. These wetlands are home to a wetland mixed broadleaf forest, and trees including Oregon ash, black cottonwood, red alder, and western red cedar. Shrubs include vine maple, salmonberry, and Nookta rose. The current access road to the site passes through this area.



Current site access point. The site is posted "No Trespassing." The road is an old logging access road and would need to be improved for public access (paving, widening, sidewalks, etc.)



A user-created trail leads to the top of the wall. This trail is steep and rocky, and would not be sustainable under intensive use. The existing terrain will make it difficult to develop a low-impact, family-friendly trail that connects the upper and lower sections.

An existing, overgrown roadbed leads from the current access point to a high viewpoint. This roadbed could be used as a future trail.



Slings hung from a Madrone tree at the top of the wall. These slings indicate the amount of climbing use that the site has experienced.